

HANDBOOK AFFECTED PAGES

Affected pages in the Owner's Handbook, Part number LRL 10 02 53 111, are as follows:

Supplement Page	Handbook Page(s)	Change detail
4	69 - 76	This vehicle is not approved for towing.
4	208	Do not fit a roof rack.
4	214 - 218	The additional battery is for armoured vehicle accessories only. Do not use for any other purpose.
5	32 - 35	This vehicle is fitted only with steering wheel and fascia airbags.
5	36 - 37	The auto lamps do not operate.
5	86 - 88	Revised driving speed of air suspension off-road height.
5	42 - 44	The rain sensor activated wipers do not operate.
5	45 - 46	Window movement is restricted. Anti-trap is not fitted. Sunroof is not an option for this vehicle.
5	92 - 93	Tyre Pressure Monitoring (TPM) System replaced with tyre pressure monitoring valve caps in non available markets.
7	64 - 65	The armoured options switch panel replaces the centre console cup holders.
10 - 12	227	Scissor jack deleted. Heavy duty trolley jack stored under rear floor. Secured in rear loadspace area.
9	231 - 232	Disregard scissor jack positioning and information.
13 - 14	199	Revised routine maintenance procedures. Daily tyre and fire suppressant system check required.
15	212	Revised wheel and tyre specification and tyre pressures. There is no temporary spare tyre with this vehicle.
16	208	Vehicle weights table revised.

Handbook affected pages	2
General information.....	4
Armoured options	7
Wheel changing.....	9
Maintenance	13
Wheels and tyres	15
Weights	16
Care of windows.....	17