Maintenance

NOTICE

Moving a headlamp unit should be undertaken only by a qualified technician. If in doubt, consult your Land Rover Retailer.

Note: To change any bulb in a headlamp unit, a cross head screwdriver and a 10mm spanner/wrench is required.

XENON LAMPS

AWARNING

High voltage is required to ignite the gas and metal vapor which are used to power Xenon lamps. Contact with this voltage can cause serious injury. Replacement or maintenance of Xenon lamps should only be carried out by suitably qualified personnel.

AWARNING

Xenon lamp units operate at a very high temperature. Ensure that the lamp units have cooled before attempting to touch them.

AWARNING

Xenon lamp units contain Mercury which is highly toxic and can be extremely harmful.



Seek advice about the correct disposal of Xenon lamp units from a Land Rover Retailer or your local authority.