2. Push the cover down firmly and then fasten the 4 turnbuckle clips, by reversing the turnbuckle removal shown in the illustration.

## **UNBLOCKING WASHER JETS**

Do not operate the washer jets during unblocking or adjustment. Windscreen washer fluid may cause irritation to the eyes and skin. Always read and observe the washer fluid manufacturers instructions.

If a washer jet becomes blocked, use a thin strand of wire to unblock the jet by inserting the wire into the jet. Make sure the wire is completely removed after unblocking. The washer jet position may also be adjusted by inserting the point of a needle into the jet and gently repositioning it.

## **CHANGING A BULB**

- All lamps, that are either LED or Xenon units, must only be replaced by a Dealer/Authorised Repairer.
- Before attempting a bulb change, make sure the ignition and the affected lamp are turned off.
- Always replace bulbs with the correct type and specification. If you are in any doubt, contact a Dealer/Authorised Repairer for advice.

**Note:** In certain territories it is a legal requirement to carry spare bulbs. A replacement bulb kit is available as an approved accessory from a Dealer.

**Note:** After replacing a headlamp bulb, the headlamp alignment should be checked with the appropriate equipment.